






١٥٦










Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9



PLATE SPRING IS IN NORMAL STATE

PLATE SPRING IS DAMAGED




Fig. 11




Fig. 12




Fig. 13




Fig. 14






Fig. 16




Fig. 17