




FIG.1A**FIG.1B****FIG.1C**


FIG.2

FIG.3A




FIG.3B




FIG.3C




FIG.3D




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG.6A




FIG.6B




FIG.6C




FIG.6D




FIG.6E




FIG.6F




FIG. 7A




FIG. 7B





FIG.8

FIG.9





FEATURE OF INSPECTION IMAGE				
FILM STRUCTURE A	PINHOLE DEFECT		BUMP DEFECT	
FILM STRUCTURE B	BUMP DEFECT	PINHOLE DEFECT		
FILM STRUCTURE C			BUMP DEFECT	PINHOLE DEFECT
FILM STRUCTURE D			BUMP DEFECT	PINHOLE DEFECT

FIG.10




FIG.11




FIG.12A




FIG.12B




FIG.14A




FIG.14B




FIG. 15A




FIG. 15B

