




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6A




FIG. 6B




FIG. 7




FIG. 8




FIG. 9




FIG. 10

9/19

AlOx coated




FIG. 11A

AZO-2 coated




FIG. 11B

10/19

ZnOx coated




FIG. 11C

Coating structure: AlOx
inner + AZO outer layer




FIG. 12A

SUBSTITUTE SHEET (RULE 26)

11/19

Coating structure: ZnOx
inner + AlOx outer layer




FIG. 12B

DEZ first AZO super-cycle coating




FIG. 12C

SUBSTITUTE SHEET (RULE 26)




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 13D




FIG. 13E




FIG. 13F




FIG. 14A

FIG. 14B

