






Fig.2







Fig.4

5/21


Fig.5



6/21


Fig.6

TRANSVERSE ABERRATION



7/21

Fig.7



8/21

Fig.8

TRANSVERSE ABERRATION







Fig.9

10/21

Fig.10

11/21

Fig.11



12/21


Fig.12



Fig.13

Fig.14

15/21


Fig.15


Fig.16

Fig.17





Fig.18


Fig.19


Fig.20

Fig.21