


Fig. 1


Fig. 1



- ◆: Polycarbonate by linking reaction (Examples 1-4 and Comparative Example 1)
- ×: Polycarbonate by a conventional melt process (Comparative Examples 2-4)
- △: Polycarbonate by an interfacial process (Reference Examples 1-4)
- “---” line: Polycarbonate by linking reaction (Examples 1-4 and Comparative Example 1)
- “—” line: Polycarbonate by an interfacial process (Reference Examples 1-4)
- $y = 0.596X + 1.184$ (Polycarbonate by linking reaction)
- $y = 0.686X + 1.145$ (Polycarbonate by an interfacial process)

Fig.2

Fig.2



- ◆: Polycarbonate by linking reaction (Examples 5-7 and Comparative Example 5)
- ×: Polycarbonate by a conventional melt process (Comparative Examples 2-4)
- △: Polycarbonate by an interfacial process (Reference Examples 1-4)

Fig. 3

Fig. 3





Fig. 4

Fig. 4



- ◆: Polycarbonate by linking reaction (Examples 11-13 and Comparative Example 7)
- ×: Polycarbonate by a conventional melt process (Comparative Examples 2-4)
- △: Polycarbonate by an interfacial process (Reference Examples 1-4)