




5 APR 2004

**Fig. 1.**

5 APR 2004

**Fig. 2.****Fig. 3.**

- 5 APR 2004





Fig. 4,

5 APR 2004

Fig. 5.

- 5 APR 2004




Fig. 6

5 APR 2004



EFFICIENCY IN CONVERTING SHAFT WORK TO FLOW WORK AT 2000, 3000, 3250 AND 4000 RPM

