




Fig. 1




Fig. 2





Fig. 3






Fig. 5




Fig. 6




Fig. 7




Fig. 8






Fig. 10

PLATE SPRING IS IN NORMAL STATE

PLATE SPRING IS DAMAGED




Fig. 11




Fig. 12




Fig. 13




Fig. 14





Fig. 15



Fi 16




Fig. 17