



Fig. 1




X-RAY DIFFRACTION PATTERN OF TITANIA-COATED ALUMINA SUPPORT AT-2

Fig. 2




COMPARISON IN DIFFERENTIAL PORE DISTRIBUTION BETWEEN SUPPORTS AS-2 AND AT-2

Fig. 3



X-RAY DIFFRACTION PATTERN OF TITANIA-MIXED ALUMINA SUPPORT AT-14

Fig. 4



X-RAY ANALYSIS PATTERN OF TITANIA-COATED ALUMINA SUPPORT AT-13