










[図3]




[図4]




[図5]




[図6]




[図7]




[図8]




[図9]




[図10]




[図11]




[図12]




[図13]




[図14]











[図15]



[図16]



[図17]



[図18]

第2貫通孔の個数 (個/100mm ²)	配線層の膨張	接続密度	総合評価
5	あり	良好	×
10	なし	良好	○
50	なし	良好	○
100	なし	良好	○
250	なし	良好	○
500	なし	低下	×
1000	なし	低下	×

[図19]

第2貫通孔の個数 (個/100mm ²)	配線層の膨張	接続密度	総合評価
10	あり	良好	×
27	なし	良好	○
500	なし	良好	○
1000	なし	良好	○
2500	なし	良好	○
3000	なし	クラック発生	×
3500	なし	クラック発生	×