

DRAWINGS

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

SAFETY STANDARDS

SITE NAME	○○ SALES FACILITY NEW CONSTRUCTION	COMPANY NAME	○○ INSULATION TECH
ACTIVITY TYPE	CEILING INSULATION (SPRAYING) WORK	WORK RANGE	B1F FLOOR TO B4F BASEMENT FLOOR

ITEMS	SAFETY STANDARDS (WITHIN RANGE)		
ACTIVITY SELF-INSPECTION ITEM	☐ COMPRESSOR INSPECTION ☐ MIXER INSPECTION ☐ MOVABLE SCAFFOLD INSPECTION		
DANGEROUS ACTIVITY IN SAME ACTIVITY SPACE	☐ PLUMBING ☐ WELDING ☐ TEMPORARY LIGHTING ☐ HIGH-SPEED CUTTER ☐ THINNER, PAINT		
PRECEDING ACTIVITY CONDITION	PRECEDING ACTIVITY NAME	SCHEDULE DIFFERENCE	PROGRESS RATE DIFFER- ENCE
SUBSEQUENT ACTIVITY CONDITION	SUBSEQUENT ACTIVITY NAME	SCHEDULE DIFFERENCE	PROGRESS RATE DIFFER- ENCE
	FIREPROOFING INSULATION (10mm)	2 DAYS	40%
DANGEROUS ACTIVITIES IN UPPER, LOWER, LEFT, AND RIGHT SPACES			

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10

RISK EVALUATION

SITE NAME	○○ SALES FACILITY NEW CONSTRUCTION	DATE	2018-10-01
ACTIVITY TYPE	FOURTH BASEMENT FLOOR MACHINE ROOM/INSULATION CONSTRUCTION (○○ INSULATION TECH)		
TODAY	POLYUREA FOAM INSULATION SPRAYING (80%, 4 PERSONS)		

CLASSIFICATION	ACTIVITY CONTENTS	RISK EVALUATION
DANGEROUS ACTIVITY WITHIN SAME ACTIVITY SPACE	☐ SPRINKLER PIPING ACTIVITY ☐ TEMPORARY LIGHTING ☐ CUTTER ☐ THINNER	SIMULTANEOUS ACTIVITY (FIRE)
SUBSEQUENT ACTIVITY CONDITIONS	☒ FIRE RESISTANT COATING (SPRAYING) ☐ FOURTH BASEMENT FLOOR MACHINE ROOM SPRAYING MATERIAL AND EQUIPMENT IMPORT (20%, 3 PERSONS)	START DELAY OF SUBSEQUENT ACTIVITY / PROGRESS RATE DIFFERENCE WITH SUBSEQUENT ACTIVITY (60%)