




FIG. 1

Profile of CS10 during a -10°C/min controlled rate freeze




FIG. 2




FIG. 3




FIG. 4

Cobblestone Morphology




FIG. 5

Disorganized Morphology




FIG. 6



FIG. 7






FIG. 8








FIG. 11




FIG. 12




FIG. 13





FIG. 14






FIG. 16




FIG. 17




FIG. 18