

Select materials, solvent, and threshold temperature
102
Compound materials below threshold temperature
104
Optionally, pelletize compounded materials
106
Mold compounded materials below threshold temperature to form a molded part
108
Leach molded part to form a leached part
110
Optionally, freeze dry leached part
112
100

FIG. 1




FIG. 2A




FIG. 2B




FIG. 3B FIG. 3A FIG. 3C




FIG. 4A




FIG. 4B




FIG. 5A

FIG. 5C




FIG. 5B




FIG. 6A




FIG. 6B