

Figure 1



Figure 2



Figure 3



Figure 4


500
502
Prepare inner surface of a battery enclosure to enhance adhesion
504
Mask unwanted areas of the battery enclosure
506
Apply a dielectric coating using a spray deposition equipment
508
Cure and dry the dielectric coating
510
Perform quality control inspections for the dielectric coating

Figure 5