


Fig. 1




Fig. 2




Figure 3




Figure 4





FIG. 5

Figure 6


UE goes into idle mode A1
UE makes measurements A2
UE goes into active mode A3
UE sends availability indicator to base station A4
Base station sends request for logged measurements A5
UE determines if any logged measurements will remain after some logged measurements sent to base station A6
If no logged measurement remain, send requested logged measurement with availability indicator indicating no further logged data A7
If logged measurements remain, send requested logged measurements with availability indicator indicating further logged data A8