FIG.1



10
H
13
15
OPERATION COMMAND UNIT
62
A
V
60
PRESSURE MEASURING UNIT
18
S
11

FIG.2




FIG.3




FIG.4




FIG.5

