




FIG. 1




FIG. 2




FIG. 3






FIG. 4



R.D.(115-1) = K0, K0, K0, K0, KF, J0, JF, J0, KF, K0, J0, K0, KF, KF, KF, KF, KF

R.D.(150-0) = K0, K0, K0, K0


FIG. 5



R.D.(115-1) = K0, K0, K0, KF, J0, JF, J0, KF,
K0, J0, K0, KF, KF, KF, KF, KF

R.D.(115-2) = KF, KF, KF, KF, KF, KF,
KF, K0, K0, K0, K0, KF,
K0, J0, J0, K0, K0, JF, JF, K0,
K0, J0, JF, JF, J0, K0,
KF, KF, J0, J0, J0, KF


FIG. 6



R.D.(115-1) = -, -, -, KF, J0, JF, J0, KF, J0, KF, J0, -, KF, KF, KF, KF, KF

R.D.(150-0) = K0, K0, K0, K0, K0

FIG. 7



R.D.(115-1) = -, -, -, KF, J0, JF, J0, KF,
-, J0, -, KF, KF, KF, KF, KF,
K0, -, -, K0, K0, JF, JF, K0,
-, J0, JF, JF, J0, -,
KF, KF, -, -, J0, KF

R.D.(115-2) = KF, KF, KF, KF, KF, KF,
KF, -, -, -, KF,
K0, -, -, K0, K0, JF, JF, K0,
-, J0, JF, JF, J0, -,
KF, KF, -, -, J0, KF


FIG. 8

115-0		<u>910-1</u> 10	<u>910-2</u> 8F
		<u>910-3</u> 0F	<u>910-4</u> 0
115-1		<u>915-1</u> 0F	<u>915-2</u> -2
		<u>915-5</u> 25	<u>915-6</u> 6
		<u>915-9</u>	<u>915-10</u>
		<u>915-11</u> 7	<u>915-12</u> 0F
		<u>915-13</u>	<u>915-14</u>
			<u>915-15</u> 0F
			<u>915-16</u> 0F
			<u>915-8</u>
			<u>915-3</u>
			<u>915-4</u>

R.D.(150-1) = 0F, -2, 25, 6, 7, 0F, 0F, 0F

R.D.(150-0) = 10, 8F, 0F, 0

FIG. 9



R.D.(150-1) = 0F, -2, 25, 6, 7, 0F, 0F, 0F

R.D.(150-2) = 256, 8, -3, 0F, 0F, 0F, 0F, 0F, 0F, 0F, 0F, 34, 0F, 0F, -35

FIG. 10

11/14




FIG. 11

12/14




FIG. 12




FIG. 13




FIG. 14