



1/4



2/4


FIGURE 2

Feed: 150N Hydrotreated slack wax
Conditions: 1LHSV, 1000 psig, 2500 scf H₂



3/4

FIGURE 3



4/4

FIGURE 4

Significant line-out time required for ZSM-48 catalyst

(Operating conditions: LHSV = 1 hr^{-1} , H_2 treat gas rate = 2500 scf/b,

Unit Pressure, = 1000 psi, Feed = HT 150 N SW)

