



[FIG. 1]




[FIG. 2]


(a) HF concentration: 0.2%




(b) HF concentration: 1.0%



(c) HF concentration: 4.0%




[FIG. 3]




[FIG. 4]





(A) Number of defects




(B) Haze deterioration amount



[FIG. 5]



[FIG. 6]



[FIG. 7]

Rotation number (rpm)

