



[Fig. 1]


Cross-Section Structure



[Fig. 2]




[Fig. 3]




Peeling occurred during the processing.
→ It is because these are not bonded or the bond strength is weak.

[Fig. 4]

Cross-Section Structure




[Fig. 5]




Abnormalities (red part) were confirmed throughout the outer periphery.

[Fig. 6]




[Fig. 7]




No abnormality was confirmed on the inside.

[Fig. 8]


Sampled Locations



[Fig. 9]



[Fig. 10]



No abnormality such as a gap was acknowledged in the bonded part.