







FIG. 2

	STEP 1 (30 min)	STEP 2 (7h30)
VESSEL 1	Repressurize 0.5 → 50 bar g	DRYING DRYING HEATING COOLING / STAND-BY (optional)
VESSEL 2	DRYING	
VESSEL 3	Depressurize 50 → 45 bar g	
VESSEL 4	Depressurize 45 → 0.5 bar g	

FIG. 3




FIG. 4




FIG. 5




FIG. 6