
200
210
SELECT ACCELERATION ENERGY AND/OR PEAK ENERGY OF SOURCE
GREATER
220
SELECT TARGET MATERIAL HAVING A NEUTRON PRODUCTION THRESHOLD ~~LESS~~ THAN THE ACCELERATION ENERGY/PEAK ENERGY
GREATER
230
SELECT COLLIMATOR MATERIAL HAVING A NEUTRON PRODUCTION THRESHOLD ~~LESS~~ THAN THE ACCELERATION ENERGY/PEAK ENERGY
GREATER
240
SELECT SHIELDING MATERIAL HAVING A NEUTRON PRODUCTION THRESHOLD ~~LESS~~ THAN THE ACCELERATION ENERGY/PEAK ENERGY
250
ASSEMBLE SOURCE

FIG. 3