




[FIG.1]




[FIG.2]




[FIG.3]




[FIG.4]




[FIG.5]



[FIG.6]




[FIG.7]







[FIG.8]

		Gw (mm)							
		1	2	3	4	5	6	7	8
G (mm)	3	B	B	A	A+	A+	A+	A+	A+
	4	B	B	A-	A	A+	A+	A+	A+
	5	B	B	B	B	A	A+	A+	A+
	6	B	B	B	B	A-	A	A+	A+


[FIG.9]




[FIG.10] (a)




[FIG.11]




[FIG.12]




[FIG.13]




[FIG.14]




[FIG.15] (a)




(b)




(c)




(d)




[FIG.16]




[FIG.17]




[FIG.18]



[FIG.19]



[FIG.20]



[FIG.21]

