







FIG. 2A




FIG. 2B




FIG. 3




FIG. 4

-----C= TOP CENTRAL AXIS
-----B= SHAFT CENTRAL AXIS
-----A= BOTTOM CENTRAL AXIS




FIG. 6




FIG. 5




FIG. 7




FIG. 8





FIG. 9






FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17






FIG. 18




FIG. 19

FIG. 20





FIG. 21






FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27A




FIG. 27B

FIG. 27C




FIG. 28




FIG. 30




FIG. 29




FIG. 31




FIG. 32




FIG. 33




FIG. 34




FIG. 35





FIG. 36



PRIOR ART

FIG. 37





FIG. 38






FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45