ABSTRACT

INTEGRATED CIRCUIT SYSTEM WITH SEALRING AND METHOD OF MANUFACTURE THEREOF

A method of manufacture an integrated circuit system includes: forming an insulation region in a base layer; filling an insulator in the insulation region around a perimeter of a main chip region; forming a contact directly on and within planar extents of the insulator; and forming an upper layer over the contact to protect the main chip region.

Fig. 2