

FIG.1




FIG.2A




FIG.2B




FIG.3A




FIG.3B




FIG.4



FIG.5A




FIG.5B




FIG.6




FIG.7




FIG. 8




FIG.9




FIG.10




FIG.11




FIG. 12A




FIG.12B




FIG. 12C




FIG.13




FIG.14A




FIG.14B




FIG. 14C




FIG. 14D




FIG.15




FIG.16




FIG.17




FIG.18A




FIG.18B










FIG.19

COMBINATION	MARKS	OUTPUT OF SENSORS
1		
2		
3		
4	