

METHODS FOR MANUFACTURING INVESTMENT CASTING SHELLS

ABSTRACT

An at least two step heating process is used to strengthen the shell of an investment casting mold including a refractory metal core. The first stage may occur under otherwise oxidizing conditions at a low enough temperature to avoid substantial core oxidation. The second stage may occur under essentially non-oxidizing conditions at a higher temperature.

Figure 1