




FIG.1




FIG. 2




FIG.3




FIG.4




FIG.5




FIG.7




FIG.8




	Marks	Outputs of sensors
1		320 <u>OFF</u> 321 <u>OFF</u>
2		320 <u>OFF</u> 321 <u>ON</u> <u>OFF</u>
3		320 <u>ON</u> <u>OFF</u> 321 <u>OFF</u>
4		320 <u>ON</u> <u>OFF</u> 321 <u>ON</u> <u>OFF</u>

FIG.9




FIG.10