




FIG.1




FIG.2






FIG.3

4. GG
 LL



LGFL




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.12




FIG.11




FIG.13

	Primary Metal Cations				
	Cu	Hg	Fe	Pb	Ag
Cu	—	X	XX	XX	XXX
Hg	≈	—	X	XX	XX
Fe	√	√	—	X	XX
Pb	√√	√√	√	—	X
Ag	√√√	√√√	√√	√	—

FIG.14




FIG.15




FIG.16




FIG.17




FIG.18