ABSTRACT

METHOD OF FORMING FINE METAL SPHERES
OF UNIFORM SIZE

A method of producing fine metal spheres (20) with a high degree of uniformity in size has the steps of cutting a fine metal wire 1 at a constant length into metal wire chips (16; 20), and heating the fine metal chips to a temperature above the melting point thereof so as to melt and spheroidize the metal wire chips.

This Sheet Has Been Replaced

THIS SHEET HAS BEEN
REPLACED