

1 / 9




FIG. 1

2 / 9




FIG. 2

3 / 9




FIG. 3




FIG. 4

4 / 9




FIG. 5




FIG. 6

5 / 9




FIG. 7




FIG. 8

6 / 9




FIG. 9




FIG. 10

7 / 9





FIG. 11



- B sintered @ 1300°C , 1wt.% NaOH + 25wt.% NaBH_4 solution
- C sintered @ 1300°C , 5wt.% NaOH + 25wt.% NaBH_4 solution
- D sintered @ 1300°C , 10wt.% NaOH + 25wt.% NaBH_4 solution
- F sintered @ 1200°C , 1wt.% NaOH + 25wt.% NaBH_4 solution
- G sintered @ 1200°C , 5wt.% NaOH + 25wt.% NaBH_4 solution
- H sintered @ 1200°C , 10wt.% NaOH + 25wt.% NaBH_4 solution
- J sintered @ 1100°C , 1wt.% NaOH + 25wt.% NaBH_4 solution
- E sintered @ 1100°C , 5wt.% NaOH + 25wt.% NaBH_4 solution
- L sintered @ 1100°C , 10wt.% NaOH + 25wt.% NaBH_4 solution

FIG. 12

9 / 9




FIG. 13




FIG. 14