


[FIG. 2]


To PDE
Straight
MIN1'D
FMU3
MIN2'D
15A
A3
To TSU
Sampling Port(G2)
HEAD PUMP
From ANU
SUBMERSIBLE BALLAST P/P (DE-BALLAST ONLY)
S.C(P)
11
27
SPOOL PIPE
A2
FMU2
MIN1'D
MIN2'D
21
120
110
10
25
12
22
23
BALLAST P/P(1300M3/HR) (BALLAST ONLY)
ECU
VOLUME
Drain
Strainer
A.P.TANK


[FIG. 3]


To PDE
Straight
FMU3
MIN1'D
MIN2'D
15A
A3
To TSU
Sampling Port(G2)
HEAD PUMP
From ANU
SUBMERSIBLE BALLAST P/P (DE-BALLAST ONLY)
S.C(P)
To PDE
11
12
10
120
110
130
26
29
140
SPOOL PIPE
A2
FMU2
MIN1'D
MIN2'D
Straight
To TSU
Sampling Port(G2)
15A
A.P.TANK
BALLAST P/P(1300M3/HR) (BALLAST ONLY)
EDU
VOLUME
Drain
T-Strainer
From ANU
To PDE
To TSU
Sampling Port(G2)


[FIG. 4]


To PDE
To TSU
A3
15A
Sampling Port(G2)
Straight
MIN1'D
FMU3
MIN2'D
HEAD PUMP
From ANU
SUBMERSIBLE BALLAST P/P (DE-BALLAST ONLY)
S.C(P)
150
11
130
29
SPOOL PIPE
A2
FMU2
EDU
VOLUME
Drain
BALLAST P/P(130CMG/HR) (BALLAST ONLY)
A.P. TANK

【Fig. 2】



【Fig. 3】



【Fig. 4】

