Abstract of Disclosure

METHOD OF REMOVING CONTAMINATIONS

A method of removing contaminations includes providing a wafer, performing an inspection or a measuring step to the wafer, and performing a baking step to re-vaporize and remove contaminations from the wafer after the inspection or measuring step.

Figure 1