




FIG. 1




FIG. 2




FIG. 3




FIG. 4

Operation name	Category	Name	Type	Type range
Transpose	Input	X	Tensor	fp 16, fp 32, int 8, uint 8, int 16, uint 16, int 32, uint 32, int 64, and uint 64
	Output	Y	Tensor	fp 16, fp 32, int 8, uint 8, int 16, uint 16, int 32, uint 32, int 64, and uint 64
	Attribute	Command	Integer list	
Attribute		Value		
Input		Temporary continuous tensor		
Output		Continuous view tensor		
Apparatus axis information		{0, 2, 1}		

FIG. 5




FIG. 6




FIG. 7