




Fig. 1




Fig. 2




Fig. 3

FIG. 1 is a schematic diagram of a mechanical assembly 100. The assembly includes a base 322 with a circular feature 328 containing a hole 330. A shaft 326 is mounted on the base, with a component 400 at its left end. A nut 332 is at the right end of the shaft. Dimensions d_5 , d_3 , d_4 , and d_6 are indicated. A coordinate system (x, y, z) is shown on the left.

FIG. 4b




FIG. 4c









FIG. 4d










FIG. 4k




FIG. 4l




FIG. 4m




FIG. 4n




FIG. 4o




FIG. 5a




FIG. 5b




FIG. 5c




FIG. 5d




FIG. 5e




FIG. 5f




FIG. 5g




FIG. 5h






FIG. 5i






FIG. 7




FIG. 7a




FIG. 8