

ABSTRACT

In a working machine (100), a plurality of diagonal members (60) includes a plurality of first diagonal members (60) for connecting a first main member (51) and a second main member (52) with each other, the first diagonal members (60) including a first nearest diagonal member (601) located nearest to a first connector (71A) connected to an end of the first main member (51). A first reinforcement part (40) extends from the first nearest diagonal member (601) to the second main member (52) or a second connector (72A) in a first specific direction for connecting the first nearest diagonal member (601) and, the second main member (52) or the second connector (72A) connected to an end of the second main member (52) with each other.