




FIG. 1

Control changes from Constant-Current to Constant-Power at max power point (In this example Force = 400g and Pmax ~ 37W)




FIG. 2




FIG. 3