

FIG. 1A




FIG. 1B






FIG. 1C

FIG.2A




HEAVE (FLATNESS)

FIG.2B



WAVINESS

FIG.2C



MICROWAVINESS

FIG.2D



ROUGHNESS
(ARITHMETIC AVERAGE)
ROUGHNESS Ra




FIG.3




FIG. 4









FIG. 5C

FIG. 5B

FIG. 5A










FIG. 6C

FIG. 6B

FIG. 6A











FIG.8C

FIG.8B

FIG.8A




FIG. 9A




FIG. 9B




FIG.10




FIG.11A




FIG.11B



FIG.11C



FIG.11D