Abstract

To solve a problem that it is difficult to improve productivity when small lot production of various types is required. In a table T including an intermediate leg unit 2 that includes a leg support 5, a stay 6, and beam connectors 7A, 7B, in which the leg support 5 has a stay attachment portion 50, the stay 6 has a plurality of beam connecting portions 6x, and is attached to the stay attachment portion 50 of the leg support 5, the beam connectors 7A, 7B are selectively attached to any one of the plurality of beam connecting portions 6x of the stay 6, and the intermediate leg unit 2 supports a portion of a top plate 1, the leg support is a specific leg support selected from at least two kinds of leg support each having a stay attachment portion 50 to which the stay 6 is attachable.

Fig. 2