

FIG. 1

2/71




FIG. 2

3/71




FIG. 3

4/71



FIG. 4

5/71



FIG. 5

6/71




FIG. 6

7/71




FIG. 7

8/71



FIG. 8

9/71



FIG. 9

10/71




FIG. 10

11/71




FIG. 11

12/71



FIG. 12A




FIG. 12B

13/71



FIG. 13A




FIG. 13B

14/71




FIG. 14B




FIG. 14A




FIG. 15C




FIG. 15D




FIG. 15A




FIG. 15B

16/71




FIG. 16C




FIG. 16D




FIG. 16A




FIG. 16B

17/71




FIG. 17A




FIG. 17B




FIG. 17C




FIG. 17D




FIG. 17E




FIG. 17F

18/71



FIG. 18

19/71



FIG. 19

20/71



FIG. 20

21/71



FIG. 21

22/71



FIG. 22A



FIG. 22B

23/71




FIG. 23

24/71



FIG. 24A




FIG. 24B

25/71




FIG. 25A




FIG. 25B




FIG. 25C

26/71









FIG. 26

27/71



28/71




FIG. 28

29/71




FIG. 29

30/71




FIG. 30

31/71




FIG. 31

32/71




FIG. 32




FIG. 33

34/71




FIG. 34

35/71




FIG. 35

36/71




FIG. 36

37/71




FIG. 37

38/71




FIG. 38

39/71




FIG. 39D




FIG. 39E




FIG. 39C



FIG. 39B




FIG. 39A

40/71




FIG. 40

41/71




FIG. 41

42/71




FIG. 42

43/71




FIG. 43

44/71




FIG. 44

45/71




FIG. 45

46/71




FIG. 46

47/71




FIG. 47

48/71




FIG. 48

49/71




FIG. 49

50/71




FIG. 50

51/71




FIG. 51

52/71




FIG. 52

53/71




FIG. 53C

FIG. 53B

FIG. 53A




FIG. 53E

FIG. 53D

54/71




FIG. 54

55/71




FIG. 55

56/71





FIG. 56

57/71



Slopes:

$$\tan \alpha = 0.27$$

$$\alpha = 15^\circ$$

$$\tan \beta = 0.25$$

$$\beta = 14^\circ$$

$$\tan \gamma = 0.094$$

$$\gamma = 5^\circ$$

FIG. 57

58/71




FIG. 58

59/71




FIG. 59

60/71




FIG. 60

61/71




FIG. 61

62/71






FIG. 62

63/71



64/71




FIG. 63C

65/71




FIG. 64B




FIG. 64A




FIG. 64C

66/71




FIG. 65B

FIG. 65A

67/71




FIG. 66B




FIG. 66A

68/71




FIG. 66D




FIG. 66C

69/71




FIG. 67

70/71




FIG. 68




FIG. 69