




FIG. 1




FIG. 2

3/45




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10a




FIG. 10b




FIG. 10c




FIG. 10d




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22a






FIG. 23




FIG. 24a




FIG. 24b




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30a




FIG. 30b




FIG. 30c




FIG. 31




FIG. 32




FIG. 33

36/45




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41

42/45




FIG. 42




FIG. 43




FIG. 44




FIG. 45




FIG. 46

This exploded perspective view shows the assembly 49, which includes a set of four parallel shafts (494, 495, 496) with various components like bushings (4941, 4951, 4961) and a complex linkage mechanism (491, 492, 493, 497) featuring springs (4931) and a lever (4971).

FIG. 48