

ABSTRACT**INK JET FAULT TOLERANCE METHOD**

A printing method identifies where parts of an image will not be printed due to device failure and if possible shifts ink dots sideways or lengthways to adjacent rows or columns so as to lessen the visual effect of failure to print at the original location.

Figure 3