

ABSTRACT

COPPER PADS FOR HEAT SPREADER ATTACH

A new method is provided for the connection of heat conducting copper pads, eliminating the need for these heat conducting pads to be connected directly to the ground ring, further eliminating the need for the ground ring to be the external ring that is provided on a surface of the package.

FIGURE 5 IS SUGGESTED FOR PUBLICATION