SYSTEM AND METHOD FOR GENERATING CARE AREAS

FOR DEFECT INSPECTION

ABSTRACT

A method of generating care areas is disclosed. An artwork file of a layout of a product is provided and a cell tree of the layout is formed. The cell tree includes a plurality of cells of the layout arranged in a hierarchical order. The method also includes defining care areas in the artwork file of the layout.

Fig.3a