ABSTRACT

METHOD FOR HANDLING A SLAG POT OR LADLE AND PYROMETALLURGICAL TOOLS

Method for handling a slag pot or ladle or pyro-metallurgical tools comprising the steps of spraying a mineral suspension onto a wall and putting into service of said slag pot or ladle or of the pyro-metallurgical tool, wherein said mineral suspension comprises calcium particles in suspension in an aqueous phase forming a calcium particle slurry containing a carbon hydrate at a content between 0.2 and 3%.

[NO DRAWING]