




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5

6/13




Fig. 6




Fig. 7




Fig. 8





Fig. 9

(a)



(b)

Not appropriate relation:
Wheel chair is directly
below a companion




Fig. 10






Fig. 11

(a)

WINQ Setup



Joystick Control



WINQ Unit
with NoIR Camera removed

(b)






Fig. 12

13/13

(a)



Interchangeable Top Base
with Steering Rod



WINQ Unit
with NoIR Camera Removed
& Top Base Replaced

(b)




Fig. 13