

Fig.1




Fig.2

Arithmetic mean values of the abundance ratios of forming materials
in the respective cross sections of polishing cloths(%)




Fig.3

Arithmetic mean values of the abundance ratios of forming materials
in the respective cross sections of polishing cloths(%)




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8

Surface of the polishing cloth of Example 1-1




Fig.9

Cross section of the polishing cloth of Example 1-1




Fig.10

Surface of the polishing cloth of Comparative Example 1-1




Fig.11

Cross section of the polishing cloth of Comparative Example 1-1




Fig.12

Surface of the polishing cloth of Example 5-1




Fig.13

Cross section of the polishing cloth of Example 5-1




Fig.14

Surface of the polishing cloth of Comparative Example 2-1




Fig.15

Cross section of the polishing cloth of Comparative Example 2-1

