

1/24




FIG. 1
PRIOR ART




FIG. 2A




FIG. 2B

2/24




FIG. 3

Fig. 4A




Fig. 4B





FIG. 4C

4/24




FIG. 5

5/24




FIG. 6
PRIOR ART

6/24




FIG. 7
PRIOR ART

7/24




FIG. 8
PRIOR ART

8/24




FIG. 9

9/24





FIG. 10



11/24




FIG. 12B




FIG. 12A

12/24




FIG. 13A
PRIOR ART




FIG. 13B
PRIOR ART

13/24




FIG. 14A




FIG. 14B




FIG. 14C




FIG. 14D

14/24




FIG. 15B




FIG. 15D




FIG. 15A




FIG. 15C




FIG. 16B

FIG. 16A

16/24




FIG. 17

17/24





FIG. 18

18/24



Lower back spacer with hollow inside

FIG. 19

19/24




FIG. 20

20/24




FIG. 21

21/24




FIG. 22

22/24




FIG. 23

23/24




FIG. 24

24/24




Fig. 25