




Fig. 1




Fig. 2






Fig. 3



$$P_{\text{Wafer}} = \approx -0.95 \text{ bar}$$

$$P_{\text{Chamber}} = 0 \text{ bar}$$

$$P_{\text{Chuck}} = \approx -0.95 \text{ bar}$$



$$P_{\text{Wafer}} = \approx -0.95 \text{ bar}$$

$$P_{\text{Chamber}} = 0 \text{ bar}$$

$$P_{\text{Chuck}} = \approx -0.95 \text{ bar}$$




Fig. 4c






Fig. 4d






Fig. 4g