

Figures





Fig. 1






Fig. 3




Fig. 4a




Fig. 4b




Fig. 4c




Fig. 4d




Fig. 5a




Fig. 5b




Fig. 5c




Fig. 5d





Fig. 6a



5

Fig. 6b





Fig. 7






Fig. 9a




Fig. 9b




Fig. 9c




Fig. 9d






Fig. 10a



5

Fig. 10b



- 1) $R = 0.2371$ $Mx = 0.2845$
 $\alpha = 0.3927$ $My = 0.0000$
1') $R = 0.7629$ $Mx = -0.2012$
 $\alpha = 0.3927$ $My = -0.2012$

Fig. 11





Fig. 12a



5

Fig. 12b




Fig. 13a

1) $R = 0.0625$ $M_x = 0.5208$ $\alpha = 0.1745$ $M_y = 0.0000$	1') $R = 0.9375$ $M_x = 1.5208$ $\alpha = 0.1745$ $M_y = -0.0000$
2) $R = 0.9375$ $M_x = -0.3409$ $\alpha = 0.2803$ $M_y = -0.1519$	2') $R = 0.0625$ $M_x = 0.6591$ $\alpha = 0.2803$ $M_y = -0.1519$
3) $R = 0.0625$ $M_x = 0.4452$ $\alpha = 0.5822$ $M_y = 0.2325$	3') $R = 0.9375$ $M_x = 1.4452$ $\alpha = 0.5822$ $M_y = 0.2325$
4) $R = 0.9375$ $M_x = 0.0000$ $\alpha = 0.5337$ $M_y = -0.5208$	4') $R = 0.0625$ $M_x = 1.0000$ $\alpha = 0.5337$ $M_y = -0.5208$
5) $R = 0.9375$ $M_x = 0.0000$ $\alpha = 0.1745$ $M_y = -0.5208$	5') $R = 0.0625$ $M_x = 1.0000$ $\alpha = 0.1745$ $M_y = -0.5208$
6) $R = 0.0625$ $M_x = -0.1519$ $\alpha = 0.2803$ $M_y = 0.3409$	6') $R = 0.9375$ $M_x = 0.8481$ $\alpha = 0.2803$ $M_y = 0.3409$
7) $R = 0.9375$ $M_x = 0.2325$ $\alpha = 0.5822$ $M_y = -0.4452$	7') $R = 0.0625$ $M_x = 1.2325$ $\alpha = 0.5822$ $M_y = -0.4452$
8) $R = 0.0625$ $M_x = -0.5208$ $\alpha = 0.5337$ $M_y = -0.0000$	8') $R = 0.9375$ $M_x = 0.4792$ $\alpha = 0.5337$ $M_y = -0.0000$
9) $R = 0.0625$ $M_x = -0.5208$ $\alpha = 0.1745$ $M_y = -0.0000$	9') $R = 0.9375$ $M_x = 0.4792$ $\alpha = 0.1745$ $M_y = -0.0000$
10) $R = 0.9375$ $M_x = 0.3409$ $\alpha = 0.2803$ $M_y = 0.1519$	10') $R = 0.0625$ $M_x = 1.3409$ $\alpha = 0.2803$ $M_y = 0.1519$
11) $R = 0.0625$ $M_x = -0.4452$ $\alpha = 0.5822$ $M_y = -0.2325$	11') $R = 0.9375$ $M_x = 0.5548$ $\alpha = 0.5822$ $M_y = -0.2325$
12) $R = 0.9375$ $M_x = -0.0000$ $\alpha = 0.5337$ $M_y = 0.5208$	12') $R = 0.0625$ $M_x = 1.0000$ $\alpha = 0.5337$ $M_y = 0.5208$
13) $R = 0.9375$ $M_x = -0.0000$ $\alpha = 0.1745$ $M_y = 0.5208$	13') $R = 0.0625$ $M_x = 1.0000$ $\alpha = 0.1745$ $M_y = 0.5208$
14) $R = 0.0625$ $M_x = 0.1519$ $\alpha = 0.2803$ $M_y = -0.3409$	14') $R = 0.9375$ $M_x = 1.1519$ $\alpha = 0.2803$ $M_y = -0.3409$
15) $R = 0.9375$ $M_x = -0.2325$ $\alpha = 0.5822$ $M_y = 0.4451$	15') $R = 0.0625$ $M_x = 0.7675$ $\alpha = 0.5822$ $M_y = 0.4451$
16) $R = 0.0625$ $M_x = 0.5208$ $\alpha = 0.5337$ $M_y = -0.0000$	16') $R = 0.9375$ $M_x = 1.5208$ $\alpha = 0.5337$ $M_y = -0.0000$

Fig. 13b




Fig. 14




Fig. 15




Fig. 16




Fig. 17a




Fig. 17b




Fig. 17c




Fig. 18a





Fig. 18b



5 Fig. 18c