




FIG. 1




FIG. 2





FIG. 3

4/36

*FIG. 4A*




FIG. 4B

6/36






FIG. 4C

7/36

*FIG. 4D*

8/36

*FIG. 4E*

9/36





FIG. 4F

10/36

*FIG. 5A*




FIG. 5B

12/36





FIG. 5C

13/36

*FIG. 5D*




FIG. 5E





FIG. 5F

16/36

*FIG. 6A*




FIG. 6B




FIG. 6C




FIG. 6D




FIG. 7A




FIG. 7B





FIG. 7C

23/36

*FIG. 7D*





FIG. 7E

25/36

*FIG. 7F*




FIG. 8A

26/36
TYPE 1 (RH SHOWN)




FIG. 8B




FIG. 9A

TYPE 2 (RH SHOWN)




FIG. 9B

27/36




FIG. 10




FIG. 11




FIG. 12




FIG. 13

28/36




FIG. 14




FIG. 15





FIG. 16




29/36



TYPES 1,2,3



THIS IS RH, R LOOP PROP

FIG. 17

*FIG. 18A**FIG. 18B**FIG. 18C*



32/36




FIG. 21A




FIG. 21B

33/36




FIG. 22

34/36




FIG. 23

35/36




FIG. 24

36/36




FIG. 25